Worley, Wesley C-FS

From:

Worley, Wesley C -FS

Sent:

Wednesday, October 17, 2018 1:40 PM

To:

Neal, Monica -FS; Farr, Cara L -FS; Cross, Darren M -FS

Cc:

Jewkes, Holly -FS; Levitan, Frederick -FS

Subject:

2520 : Terwilliger Fire - Burned Area Emergency Response Report

Link to Work Package FY 2019 - 297825: https://ems-portal.usda.gov/sites/fs-wo-csa1/Mercury/layouts/15/DocIdRedir.aspx?ID=CV22QSYQPP7S-2-834223

Please save this e-mail. The Mercury Correspondence Archive is difficult to use, and the link above will be the best method of recovering the document for future reference.

Thank you,



Wesley Worley Executive Assistant

Forest Service Willamette National Forest

p: 541-225-6314 f: 541-225-6222

wesleycworley@fs.fed.us

3106 Pierce Parkway, Suite D Springfield, OR 97477

www.fs.fed.us



Caring for the land and serving people

Malo periculosam, libertatem quam quietam servitutem



Willamette National Forest Supervisor's Office 3106 Pierce Parkway Suite D Springfield, OR 97477

File Code:

2520

Date:

October 17, 2018

Route To:

Subject:

Terwilliger Fire - Burned Area Emergency Response Report

To:

Regional Forester

Enclosed please find the initial Burned Area Emergency Response (BAER) Report for the Terwilliger Fire. This report describes the post-fire critical values at risk, threats and the assessed risks to those values, proposed emergency treatments and funds requested to mitigate damage or loss of those values.

The Terwilliger Fire started from a human cause on August 19, 2018. The fire has burned approximately 11,555 acres on the McKenzie River Ranger District.

The Willamette National Forest worked closely with local citizens, adjacent land owners, State and local agencies to coordinate safety and protection of resources during fire suppression activities. This coordination continued through the BAER assessment and will continue as we move forward with post-fire assessments and potential treatments. The Terwilliger Fire burned area is a high recreational use area, and there is utmost concern for human life and safety from post-fire conditions.

I recommend the enclosed land, road, trail and safety treatments as emergency measures needed to protect human life and property, as well as significant resource and ecosystem values within the burned area. I am requesting funds in the amount of \$56,300 to implement the proposed treatments on national forest lands.

I have reviewed the plan and determined that this is an emergency in nature and the actions will assist in reducing the risk to the values identified within and adjacent to the Terwilliger Fire.

DARREN M. CROSS for

TRACY BECK

Forest Supervisor

Enclosure

cc: Holly Jewkes, Darren Cross, Cara Farr

FS-2500-8 (6/06) Date of Report: October 17, 2018

BURNED-AREA REPORT

(Reference FSH 2509.13)

PART I - TYPE OF REQUEST

	,
А. Тур	e of Report
j	X] 1. Funding request for estimated emergency stabilization funds] 2. Accomplishment Report] 3. No Treatment Recommendation
В. Тур	ė of Action
[> measu	(] 1. Initial Request (Best estimate of funds needed to complete eligible stabilization res)
[] analysi	2. Interim Report # [] Updating the initial funding request based on more accurate site data or designs [] Status of accomplishments to date
[] 3. Final Report (Following completion of work)

PART II - BURNED-AREA DESCRIPTION

A. Fire Name: Terwilliger B. Fire Number: OR-WIF-180227

C. State: Oregon D. County: Lane County

E. Region: Pacific Northwest (R6)

F. Forest: Willamette National Forest

G. District: McKenzie River Ranger District H. Fire Incident Job Code: P6L3SB19 0618

containment)

I. Date Fire Started: 8/19/2018

K. Suppression Cost: \$22,835,421 as of 10/11/2018

- L. Fire Suppression Damages Repaired with Suppression Funds
 - 1. Roads improved as fire line: 38.3 miles
 - 2. Dozer lines not on roads: 3.0 miles; all to have drainage installed through suppression repair.

J. Date Fire Contained: 80% contained (final

- 4. Hand lines: 4.7 miles; all to have drainage installed through suppression repair.
- 5. Miles of road treated, non-fire line: 74.5 miles
- 6. Other drop points, staging areas, helispots, safety zones, pump chances, spills, etc.

M. Watershed Number:


- o 6th Field Watersheds
- 170900040304 Rebel Creek South Fork McKenzie River
- 170900040305 French Pete Creek
- 170900040306 East Fork South Fork McKenzie River
- 170900040307 Cougar Reservoir South Fork McKenzie River

Total acres, Soil Burn Severity (SBS) by Subwatershed

	Subwa	tershed Soil Burn Severity								
Subwatershed Name	Acres Bur	% % med	- Y	Low (acres)			-	burned cres)		
Cougar Reservoir-South Fork McKenzie River	19,513	(40%)	172	(1%)	1,145	(6%)	5,237	(27%)	1,335	(7%)
East Fork South Fork McKenzie River	12,926	(7%)	0	(0%)	12	(0%)	476	(4%)	444	(3%)
French Pete Creek	20,121	(6%)	0	(0%)	27	(0%)	804	(4%)	436	(2%)
Rebel Creek-South Fork McKenzie River	16,937	(8%)	0	(0%)	80	(0%)	951	(6%)	344	(2%)
Grand Total	69,497	(16%)	172	(0%)	1,264	(2%)	7,468	(11%)	2,559	(4%)

N. Total Acres Burned:

NFS Acres (11,463) Other Federal (0) State (0) Private (0)



Terwilliger Fire Soil Burn Severity

O. Vegetation Types:

The vegetated habitat in the Terwilliger fire area varies along an elevational and aspect gradient. Four major plant series are present: Douglas-fir, grand fir, western hemlock, and Pacific silver fir. Douglas-fir series is typically found on warm, dry sites and lower to mid elevations. West-side grand fir tends to occupy cool, dry and well drained soils. Sites usually have rocky or ashy soils and are found on lower to mid elevations. Western hemlock forests are found on warm, moist sites where snow packs are usually not deep or long lasting. They are found on lower to mid elevations. Pacific silver fir is located on mid to upper elevations. The sites are cool, and wet with persistent snow packs that shorten their growing season.

Deciduous shrubs that commonly dominate or co-dominate the understory are Alaska huckleberry (*Vaccinium alaskaense*), big huckleberry (*V. membranaceum*), red huckleberry (*Vaccinium parvifolium*), rhododendron (*Rhododendron macrophyllum*), vine maple (*Acer circinatum*), devil's-club (*Oplopanax horridus*), baldhip rose (*Rosa gymnocarpa*), currants (*Ribes* spp.), and creeping snowberry (*Symphoricarpos mollis*). Important evergreen shrubs include salal (*Gaultheria shallon*), wintergreen (*Gaultheria ovatifolium*), dwarf Oregon grape (*Mahonia nervosa*), Pacific rhododendron (*Rhododendron macrophyllum*), beargrass (*Xerophyllum tenax*), and Oregon boxwood (*Paxistima myrsinites*).

P. Dominant Soils:

Dominant soils inside the fire perimeter are predominantly andisols and inceptisols with lithic modifiers. They are composed of shallow gravelly loamy sands formed from residuum and colluvium from volcanic parent materials. These areas consisted of steep slide-slopes and ridges with slopes ranging from 30 to 90 percent. The infiltration rate of these soils are high due to the coarse texture and gravel content.

Q. Geologic Types:

The burned area landscape is split between two distinct volcanic subgroups of the Cascade Range geologic province, which was split by a extensional down-dropped graben seven million years ago. The Cougar Fault trends north-south, and trends through the western edge of Cougar Reservoir (former South Fork McKenzie River valley bottom). East of the Cougar Fault is the High Cascades, Pliocene to present in age, dominated by large stratovolcanoes, shield volcanoes, recent lava flows, cinder cones and tephra deposits. Within the burned area, High Cascade lava flow remnants cap ridges of the older underlying, West Cascades volcanics. The High Cascades have been highly sculpted by Pleistocene glaciers, with abundant till and glacial landforms. West of the Cougar Fault, the Western Cascades, Eocene to Miocene aged, are primarily composed of andesitic to basaltic volcanic lava flows, mudflows and tephra with steep, dissected mountain slopes. West Cascade slopes of east aspect, west of of Cougar Reservoir, are geologically mapped as mantled by deep-seated landslide terrain. Earthflows and slumps at the toe of Boone Creek have experienced recent activity. Subsurface hydrothermal circulation is expressed at the ground surface at Terwilliger Hot Springs.

R. Miles of Stream Channels by Order or Class:

Stream Type	Miles
Intermittent Stream	104
Perennial Stream	34
Grand Total	138

S. Transportation System

Trails: 12.4 miles

Wilderness: 8.8 miles

Non-Wilderness: 3.6 miles

Roads: See Table Below

Roads by Operational Maintenance	Level
Operational Maintenance Level	Grand Total
1 - BASIC CUSTODIAL CARE	8.4
(CLOSED)	
2 - HIGH CLEARANCE VEHICLES	25.3
3 - SUITABLE FOR PASSENGER CARS	2.3
4 - MODERATE DEGREE OF USER	0.3
COMFORT	
5 - HIGH DEGREE OF USER	10.0
COMFORT	
DECOMMISSIONED	0.1
Non FS Roads	0.1
Grand Total	46.5

PART III - WATERSHED CONDITION

A. Burn Severity (acres):

Soil Burn Severity	Acres	Percent of Burned Area
Unburned	2,560	22.3%
Low	7,468	65.1%
Moderate	1,262	11.0%
High	173	1.5%
Total	11,463	100.0%

B. Water-Repellent Soil (acres):

Water	Acres
Repellency	
High	1,435
Moderate	7,468
Low	2,560

C. Soil Erosion Hazard Rating (acres):

265 (low) 7,280 (moderate) 3,918 (high)

D. Erosion Potential: (tons/acre) from Disturbed WEPP model (Elliot, RMRS)

Year	Unburned	Low	Moderate	High
1st	0	0.3	0.93	1.31

E. Sediment Potential: Not calculated – expected to be low based on a) the fairly low (13% combined) percentage and patchy distribution of moderate and high soil burn severity across the burned area; 2) the low erosion potential figures generated by the WEPP model; and c) the common presence of remnant live vegetation and ground cover downslope of most moderate and high burn severity areas. Consequently, sediment delivery potential is judged to generally be low, and sedimentation is not likely to measurably or adversely affect downstream and downslope resources such as aquatic habitat, drinking water quality, or reservoir capacity. Local modest and transitory effects may be expected during the first winters following the fire.

PART IV - HYDROLOGIC DESIGN FACTORS

A. Estimated Vegetative Recovery Period, (years): 3 – 5 years

B. Design Chance of Success, (percent): 80%

C. Equivalent Design Recurrence Interval, (years): 2 years

D. Design Storm Duration, (hours): 24 hours

E. Design Storm Magnitude, (inches): 3.5 – 4.2 inches

F. Design Flow, (cubic feet / second/ square mile): 40.63 cfs/mi²

G. Estimated Reduction in Infiltration, (percent): 12.5%

H. Adjusted Design Flow, (cfs per square mile): 41.16 cfs/mi²

PART V - SUMMARY OF ANALYSIS

A. Describe Critical Values/Resources and Threats:

Hydrologic Response:

The Terwilliger Fire burned primarily within the Cougar Reservoir – South Fork McKenzie River watershed and in the watersheds of smaller tributaries to the South Fork McKenzie River. The watershed response in the burned area is expected to include an initial flush of ash and fine sediment, rill and gully erosion in drainages and steep slopes within the burned area, as well as increased peak flows, channel scouring, and sediment deposition. Responses are expected to be most evident during initial larger storm events immediately after the fire. Thereafter, responses are expected to become less apparent as vegetation is reestablished, providing ground cover, increasing surface roughness, and stabilizing and improving the infiltration capacity of the soils.

Minor increases in runoff are expected in watersheds within the burned area. This is due to the very low amount of moderate and high soil burn severity within the burn area (13%). The increases in flow could lead to plugged culverts, flows over road surfaces, and erosion or deposition along road surfaces and ditches.

Hydrologic design factors used to analyze the effects of the Terwilliger Fire considered the vegetative recovery period to be 3 to 5 years; treatment chance of success as 80%. Storm recurrence interval of 2 years and 24-hours yielded a design storm magnitude of 3.5 – 4.2 inches of rainfall. Estimated reduction in infiltration was based on the percentage of highly hydrophobic soil in the burn area, which was determined to be 12.5%. Pre-fire design flow was estimated at 40.63 cubic feet per second per square mile and post-fire design flow was estimated at 41.16 cubic feet per second per square mile. These values vary by watershed analyzed and are described in detail along with the analysis methodology in the hydrology and watershed specialist report.

Erosional Response

The change in erosion potential and sediment yield from pre- to post fire conditions was estimated using the Forest Service Disturbed Water Erosion Prediction Project (WEPP) model. The general data requirements for Disturbed WEPP are climate data, soil texture, rock fragments, general vegetation type, slope gradient, horizontal slope length and burn severity. This tools are useful for comparing the relative difference between pre- and post-fire erosion potential.

Averaged model estimates indicate that overall, there could be hillslope erosion increase of 0.93 - 1.31 tons per acre basis in the first year post-fire from ground where soil burn severity was moderate or high. It is assumed only a portion of sediment will be delivered based on field observations such as; slope roughness, high amount of surface rock fragments and downed large woody debris that would function as sediment delivery interrupters. The high burn severity areas are mostly buffered by moderate and low burn severity, providing a buffer for sediment delivery. These estimated output numbers, along with low amount of high burn areas, as well the mosaic of the burn, indicate that large-scale sediment response should not be expected.

Geologic Response

Modeling results generally support field observations that indicate there will be limited post-fire geologic response from a 10-year recurrence interval storm event. Only 7% of drainages have a probability greater than 0.40 for the occurrence of debris flows. Drainages at highest risk for debris flow initiation include Boone Creek, unnamed drainage north of Slide Creek, unnamed drainage between Slide and Smith Creeks, and Smith Creek (see Figure 3 below). The model design precipitation event is a 15-minute – 24mmh (short duration - high intensity storm) – these types of events are less typical for this western Oregon compared to the intermountain area. The western Cascades receive longer duration storms of lower intensity which generate most debris flows.

Initial observations in the field and from aerial reconnaissance indicates the drainages highlighted have a lower likelihood of debris flow discharge than the model predicts, due to sinuosity of stream channels and roughness of channels. Nonetheless, these channels may present at least the possibility of generating damaging debris flows under known historic conditions.

FS-2500-8 (6/06) Date of Report: October 17, 2018

tical Values:

table below is Exhibit 02 from FSM 2523.1. This matrix was used to evaluate the risk level for each critical value identified during this BAER assessment. Se ?3.1 for additional information.

ability Magnitude of Consequences	Image Major Moderate Minor	RISK	Likely Very High Very High Low	(ely Very High Low	sible High Intermediate Low	kelv Intermediate Low Very Low
Probability	of Damage	or Loss	Very Likely	Likely	Possible	Unlikely

below is a summary of the values which were identified as 'critical' per Exhibit 01 from FSM 2523.1 within and along the Terwilliger Fire area, as well as the standard of damage or loss, magnitude of consequences and the resulting level of risk. Some non-critical or non-BAER values are included where a or controversy merits their inclusion as discussion items. Red shaded cells are those values that rated out as "very high" or "high" risk. Yellow shaded cells ite" risk and green cells rated out "low" or "very low".

Sritical Value	Threat to Critical Value	Probability of Damage or Loss	Magnitude of Consequence	Risk	Treatment	Notes
SR 1900	Road failure or diversion at stream crossings and drainage culverts along Road 1900 could cause substantial property damage	Likely: Sediment and wood delivery from many hillslopes with M and H SBS is likely to enter road drainage structures.	Moderate: If road failure or diversion occurred at high risk stream crossings, the loss of property would be considered moderate. Others would require	High	Storm Inspection and Response (RT2)	ML 5 important road, Byway; Forest not like full year; High/Mod SI drainage has increase flows

			cleaning.			
FSR 1900	Post-fire increase in rockfall expected along important ML 5 road with heavy vehicle traffic	Possible: Due to the large area of potential rockfall, it is possible that a motorist, cyclist, or hiker could get struck by falling or already fallen rock, trees, or debris. Common rockfall will increase post-fire.	Major: If a motorist were to encounter a rockslide unawares, major injury or loss of life could occur.	High	Road Hazard Signs (P1a)	Some scaling occurre to reduce risk of rocl still needed to prote
FSR 1900-500	Road failure or diversion at stream crossings and drainage culverts along Road 1900-500 could cause substantial property damage	Likely: Sediment and wood delivery from many hillslopes with M and H SBS is likely to enter road drainage structures.	Moderate: Crossings have variable degrees of susceptibility to plugging or other damage, some portion would require cleaning.	High	Storm Inspection and Response (RT2)	ML 2/3; High/Mod Si fill/catchment basins USACE about supplei upgrade road
FSR 1985-115	Post-fire hazards present, including unstable rock, soil and hazard trees recommend closure (with existing gate)	Possible: Much of the road passes through moderate or high SBS where instability is common and debris hazards are prevalent.	Major: Consequences of encountering post-fire hazards such as rocks, trees or failed road prism on this narrow ML2 road could be fatality or serious injury.	High	P10 (Closure)	ML 2; High/Mod SBS landslide and tensior
Terwilliger Hot Springs	Vault toilets burned exposing hazardous material (human	Very Likely: Vaults are full and exposed by the fire;	Moderate to Major: Minor to serious	Very High	Hazardous	-

Ψ	excrement)	release would contaminate soils and groundwater near human water contact recreation area.	illness could occur from exposure to infectious waste.		Materials (P5)	
Terwilliger Hot Springs	Hot springs rock wall is adjacent to stream with increased movement of debris that could block stream and cause avulsion into the sequence of hot springs rock pools and pose a threat to public; Hazard trees present	Possible: The drainage upslope of the site is projected to have only a minor flow increase, but there is abundant mobile debris on the slopes and in the channel.	Major: Impact from falling rock, flood debris or hazard trees could cause serious injury or death.	High	Site Closure (P10)	
3319 Rider Creek Trail	Post-fire hazards present, including unstable rock, soil and hazard trees.	Possible: Mostly moderate SBS, steep slopes above trail, many burned and leaning trees	Major: Impact from falling rock, debris or hazard trees could cause serious injury or death.	High	Trail/Recreati on Hazard Signs (P1b)	
3319 Rider Creek Trail	Wooden cribs burned, leaving trail at high risk of failure	Very Likely: Due to very steep slopes (~45%) above and below trail with High/Mod SBS, there is a very high likelihood of trail failure with winter runoff	Moderate: Due to the steep slopes, if trail failure occurs, material will have to be imported to properly reconstruct. Property loss would be moderate.	Very High	Trail Infrastructure Protection (RT14)	Construct temporary stabilize trail tread
3308 East Fork Trail	Post-fire hazards present, including unstable rock, soil and hazard trees.	Possible: steep slopes above trail, many burned and leaning trees, mobile debris.	Major: Impact from falling rock, debris or hazard trees could cause serious injury or	High	Trail/Recreati on Hazard Signs (P1b)	

				Hazard signs will be put-in.
	Trail/Recreati on Hazard Signs (P1b)	Trail/Recreati on Hazard Signs (P1b)	Drainage (RT13)	Trail/Recreati on Hazard Signs (P1b)
	High	High	Very High	High
death.	Major: Impact from falling rock, debris or hazard trees could cause serious injury or death.	Major: Impact from falling rock, debris or hazard trees could cause serious injury or death.	Moderate: Due to the steep slopes, if trail failure occurs, the trail will have to be completely reconstructed. Therefore, the loss of property would be considered moderate.	Major: Impact with channel hazards could cause serious injury or death.
	Possible: steep slopes above trail, many burned and leaning trees, mobile debris.	Possible: steep slopes above trail, many burned and leaning trees, mobile debris.	Very Likely: Due to very steep slopes (~50%) above and below trail with Mod SBS, there is a very high likelihood of trail failure with winter runoff.	Possible: If boaters are unaware of the post-fire hazards in the river that have already occurred, such as downed trees and rocks, it is possible that they could get in a situation that could cause serious injury or death.
	Post-fire hazards present, including unstable rock, soil and hazard trees.	Post-fire hazards present, including unstable rock, soil and hazard trees.	Trail infrastructure damage or loss expected with increase in post-fire runoff and erosion	Post-fire hazard trees will continue to fall into the river causing significant threat to boaters
	3329 Lowder Mountain Trail	3311 French Pete Creek Trail	3311 French Pete Creek Trail	South Fork McKenzie River

Wild and Scenic Study water supply; Hydrop Dam	Wild and Scenic Study water supply; Hydrop Dam		Treatments to reduce benefit bull trout
No Treatment	No Treatment	None	None
Low	Low	Intermediate	Very Low
Minor: Because increased wood loading is a natural process, the impact to ORVs is considered minor. (There is, however, a high risk to Life and Safety, which has been addressed above.)"	Moderate: Contamination above acceptable levels might result in damage to treatment facilities or interruptions in service.	Moderate: Soil loss might impede vegetative recovery, but not create irretrievable ecosystem changes.	Minor: Because there is no bull trout spawning in areas
Likely: Although increases in flow, sediment, and nutrient loads are projected to be minor, a substantial increase in large woody material in the river has already been observed and more is expected to occur in the near future. This increase in wood loading is likely to eliminate recreational boating opportunities, which affects the Recreation ORV	Unlikely: Burned area near Cougar Reservoir is quite far (50 miles) from the water supply intake	Possible: Low burn severity in majority of fire; forest floor intact; nutrient inputs from needle cast	Unlikely: Waterbodies occupied by bull trout are not projected to receive a large
Potential for increased flows, sediment, debris, and nutrient loads and impacts to ORVs (Scenery, Recreation, Fish and Prehistoric)	Potential for increased flows, sediment, debris and nutrient loads to impact drinking water 50 miles downstream	Decrease in soil productivity	South Fork McKenzie River and Cougar Reservoir - very important for rearing, foraging,
South Fork McKenzie River above Cougar Reservoir (Wild and Scenic Study River)	South Fork McKenzie River below Cougar Reservoir (Municipal Water Supply)	Soil Productivity	Bull Trout

adults South Fork McKenzie River - very important for spawning and rearing; French Pete Creek - important for spawning and rearing; Cougar Reservoir - important for rearing; East Fork of the South Fork — not important for spawning or receive a large increase in rearing Mass wasting or road failure/diversion could deliver large amounts of sediment which could have detrimental effects to eggs, fry, and juveniles Increased temperature, flows,
sediment, debris flows, sediment, debris flows and nutrient loads may impact habitat and water quality in South Fork and Cougar Reservoir; Mass wasting or road failure/diversion could deliver large amounts of sediment which could have

	Habitat.					
Spring Chinook Salmon Critical Habitat	Increased temperature, flows, sediment, debris flows and nutrient loads may impact habitat and water quality; Mass wasting or road failure/diversion could deliver large amounts of sediment which could have long-term impacts to Critical Habitat;	Unlikely: Chinook CH is not projected to receive a large increase in temperature, flows, sediment, or nutrient loads	Moderate: Because the South Fork is a very important spawning stream, impacts could have considerable, longterm effects to the local population.	Low	None	Treatments to reduce benefit spring Chinoo
Quality and quantity of remaining Northern Spotted Owl Critical Habitat and suitable habitat	Continued loss of habitat from post-fire stress, wind and storm events and post-fire insect and disease	Possible	Minor: The territories have not supported nesting owls in recent years likely due to the suboptimal habitat conditions prior to the fire.	Low	None	Overall low degree of terms of post-fire effeminor loss of habitat watershed processes landsliding in higher bytches), in addition tprojected tree mortal causes
Heritage Resources	Impacts to heritage resources from post-fire effects, including threats from erosion or unauthorized removal of artifacts	Possible: Some Sites have been buffered and are unlikely to be exposed. There are some unsurveyed sites that may be affected.	Undetermined	Undetermine d	None at this time	No heritage assessme There are known site: area. The District arch risk is low. Some know noted and buffered d suppression activities

						removal), and are ur to post-fire effects. exposed sites along Slide Creek Campgrc heritage REAF. The Lassume responsibilit measures if needed, assessment is possib evident.
Native Plant Communities	Noxious weeds at high risk of expansion and impact to native communities	Very Likely: Existing weed populations, large amounts of fire- and suppression-related disturbance, nearby native populations are already affected to various degrees.	Major: Aggressive invasive weeds (particularly false brome and spotted knapweed) if established are likely to cause major disruption of native plant communities.	Very High	Invasives EDRR (L1a, L1b)	EDRR in danger tree be covered under su code). Other suppre: as dozer and hand lir with BAER funds.

B. Emergency Treatment Objectives:

The primary objective of this Burned Area Emergency Response Report is to recommend prompt actions deemed reasonable and necessary to effectively protect, reduce or minimize significant threats to human life and property and prevent unacceptable degradation to natural and cultural resources. The application of these BAER treatments are expected to minimize on-site and downstream damages to the identified critical values previously mentioned. The emergency treatments being recommended by the Terwilliger Fire BAER Team are specifically designed to achieve the following results:

Proposed Land Treatments

The objective of the land treatments are to:

 Promote and protect native and naturalized vegetative plant communities by reducing the spread of noxious weeds (L1a – Early Detection and Emergency Response (EDRR) - Burned Area, L1b – EDRR - Fire Suppression Features).

Proposed Channel Treatments:

There are no proposed channel treatments.

Proposed Road and Trail Treatments

The objective of the road and trail treatments are to:

- 1. Protect road and trail investments from becoming impassible and damaged due to increased post-fire runoff (RT2 Storm Inspection and Response Roads 1900, 1900-500; RT14 Trail Infrastructure Protection 3311 French Pete Trail, 3319 Rider Creek Trail).
- 2. Reduce sedimentation into streams degrading water quality (RT2 Storm Inspection and Response, RT13 Trail Drainage 3311 French Pete Trail, RT14 Trail Infrastructure Protection 3319 Rider Creek Trail.

Proposed Protection/Safety Treatments:

The objective of the protection/safety treatments are to:

- 1. Protect human life and safety by raising awareness through posting hazard warning signs at recreation sites, trailheads (3308 East Fork Trail, 3311 French Pete Trail, 3319 Rider Creek Trail, 3329 Lowder Mountain Trail) and when entering the burned area and traveling Aufderheide Scenic Byway (Road 1900) (P1a Road Hazard Signs, P1b Trail/Recreation Hazard signs).
- 2. Remove and cleanup hazardous human waste from burned toilet vaults at Terwilliger Hot Springs (P5 Hazardous Materials).
- 3. Protect infrastructure investment of Terwilliger Hot Springs pools (P6 Infrastructure Protection).
- 4. Protect human life and safety by temporary closure of Road 1985115 (existing gate) and Terwilliger Hot Springs recreation site (P10 other Administrative Closure).

C. Probability of Completing Treatment Prior to Damaging Storm or Event:

Land 70%

Channel N/A

Roads/Trails 75 %

Protection/Safety 90 %

D. Probability of Treatment Success

Tuestment	Years after Treatment				
Treatment	1	3	5		
Land	70	75	80		
Channel	NA	NA	NA		
Roads/Trails	80	85	90		
Protection/Safety	85	90	95		

E. Cost of No-Action (Including Loss) - for roads, trails, hot springs infrastructure: \$566,258

Derived from: Estimated Valuation Of Property x Probability Of Loss Without Treatment

- F. Cost of Selected Alternative (Including Loss): \$56,350
- G. Skills Represented on Burned-Area Survey Team:

[x] Hydrology	[x] Soils	[x] Geology	[] Range
[] Forestry	[x] Wildlife	[] Fire Mgmt.	[x] Engineering
[] Contracting	[] Ecology	[] Botany	[] Archaeology
[x] Fisheries	[] Research	[] Landscape Ar	rch [x] GIS

Team Leader: Fred Levitan

Email: flevitan@fs.fed.us

Phone: (541) 225-6366

Team Members:

Team Member	Specialty
Fred Levitan	Team Leader
Kate Meyer	Assistant Team Leader, Fisheries
Sarah Brame	Soils
Wendy Peterman	Soils (t)
Chris Stewart	Hydrology
Andrew Montgomery	Hydrology (t)
Bart Wills	Geology
Dylan McCoy	Recreation/Trails
Wayne Chevalier	Recreation/Trails
Danny Matthews	Engineering
Joe Doerr	Wildlife
Sarah Ward	Botany
David Keenum	GIS
Dorothy Thomas	GIS

H. Treatment Narrative:

Land Treatments:

L1a - Invasive Weed Detection and Treatment (standard BAER):

The Terwilliger Fire occurred in an area that has approximately 300 acres of existing mapped weed infestations and experiences high volumes of traffic by the public. Under BAER protocol for Invasive plant detection and treatment, the focus will be on non-infested trails into the Three Sisters Wilderness where there is a high likelihood of spread of invasive plants from hikers passing through infested areas enroute to the wilderness. High and moderate burn severity areas will be targeted. There are approximately 46 acres along Trails 3329, 3330, and 3311, which enter the wilderness from roads 1900-500 and 1900. These roads are within ¼-mile of National Forest Wilderness and have large existing populations of aggressive invasive species such as false brome and spotted knapweed, which are a threat to invade and seriously degrade the intact wilderness plant communities.

EDRR in burned areas (L1a) will occur on approximately 46 acres and estimated invasive plant treatments to occur across 7 acres (~15%). The average cost/acre of the combined treatment types is \$153/acre. **Total request for L1a is \$7,050.**

L1b - Invasive Weed Detection and Treatment (fire suppression disturbance)

Linear and small areal features disturbed by fire suppression (blading and scraping) are eligible for BAER funding as they may be available after suppression repair funds (P-code) are no longer available. For the Terwilliger Fire, it is proposed to survey 36 acres of bladed dozer line and scraped (hand line) linear features, and 12 acres of bladed small areal features (staging areas, drop points, helipads, safety zones, etc.) for a total of 45 acres. An estimated 40%, or 19 acres of these would require treatment. The unit cost would go up to \$239/acre. Suppression repair areas including dozer lines, landings and helipads are scattered throughout the burned area and often intersect inventoried sites and are near sensitive plant locations (see BAER guidance paper on Invasive Plant Threats for support of surveys in suppression areas). **Total request for L1b is \$11,450.**

**Additional sites within danger tree removal areas where equipment drove off road will be seeded, surveyed and treated using suppression repair dollars (P-code)

EDRR Treatment Cost - Contract	Units	Unit Cost	# of Units	Total Cost
Invasive Plant Surveys (L1a)	Acres	\$100.00	46	\$4,600
Invasive Plant Treatments (L1a)	Acres	\$350.00	7	\$2,450
Invasive Plant Surveys (L1b)	Acres	\$100.00	48	\$4,800
Invasive Plant Treatments (L1b)	Acres	350.00	19	\$6,650
Total Treatment Cost	Acres	\$197.00	94	\$18,500

Channel Treatments: None proposed.

Road and Trail Treatments:

Road Treatments:

RT2- Storm Inspection and Response: Storm inspection/response will keep culvert and drainage features functional by cleaning sediment and debris from in and around features between or during storms. This work will be accomplished through Forest Service Road Crew, equipment rental, and general labor. Total request is for \$7,200.

Locations:

FSR 1900000, FSR 1900500, FSR 1985115

Treatment	Units	Unit Cost	# of Units	Total Cost
Storm Inspection and Response	Days	\$1,800	4	\$7,200

Trail Treatments:

RT13 – Trail Drainage: Treatment Description - Work will include tread leveling and repair, including removal of soil deposits from erosion and runoff, and trail re-benching and/or outsloping. This work is necessary to retain the investment in the trail prism – replacement costs if it is lost would greatly exceed the cost of temporary stabilization (see analysis in the Recreation specialist report and the VAR Lite benefit-cost analysis, both in the project record.) Trail program manager and crew lead time for coordination with partners and contractors regarding trail conditions is included. Work will be completed with force account labor (reduced cost) if that is available at the time implementation is necessary, but should be completed before the onset of the winter rainy season. Total request is for \$5,000.

Treatment Cost – (segments of French Pete Trail 3311 downslope of moderate burn severity areas.)

		Costs Es	stimate (per mile)	
Item	Cost	Quantity (Day)	Total	Notes
Contractor	\$1,000	10	\$10,000	Project Implementation
		Total:	\$10,000 per mile	

Trail Name & Number	Units	# of Units	Unit Cost	Total Cost
French Pete Trail 3311	Miles	.5	\$10,000	\$5,000

RT14 – Trail Infrastructure Protection: Work is similar to RT13, but includes temporary retaining walls to replace the wooden cribwalls burned in the fire. Absent these, the trail prism would quickly be eroded away during winter runoff from the moderate soil burn severity area upslope. The Forest would later replace these temporary supports with permanent structures using program funds. Trail program manager and crew lead time for coordination with partners and contractors regarding trail conditions is included. Work will be completed with force account labor (reduced cost) if that is available at the time implementation is necessary, but should be completed before the onset of the winter rainy season. Total request is for \$7,500.

Treatment Cost – (entire Rider Creek Trail 3319 to Terwilliger Hot Springs.)

		Costs Es	stimate (per mile)	
Item	Cost	Quantity (Day)	Total	Notes
Contractor	\$1,500	10	\$15,000	Project Implementation
		Total:	\$15,000 per mile	

Trail Name & Number	Units	# of Units	Unit Cost	Total Cost	
French Pete Trail 3311 Miles		.5 \$15,000		\$7,500	

Protection/Safety Treatments:

P1a – Road Hazard Signs: Signs will inform users of the dangers associated with entering and recreating within the burned area. Total request is for \$1,200.

Locations: Small hazard warning signs located at intersections of FSR 1900000 and the fire perimeter. 1 sign for each direction of travel.

Treatment	Units	Unit Cost	# of Units	Total Cost
P1 - Installation of warning sign 30x48	Sign/Post	\$600	2	\$1,200

P1b – Trail/Recreation Hazard Signs: Treatment Description - Install warning signs to alert visitors of burned area post-fire effects on trails, at campsites, and at dispersed and developed use sites, to include trailheads, campgrounds, the Terwilliger Hot Springs visitor kiosk, and a popular boat launch site on the South Fork McKenzie River near French Pete Campground.

Treatment Cost: The unit cost of the sign includes labor cost for ordering and installation. Estimated 1 day needed for total sign installation time. Program management costs are also included in the unit costs. **Total request is for \$4,400**.

Treatment	Units	# of Units	Unit Cost	Total Cost
Trail warning signs for wilderness trailheads	Each	5	\$400	\$2,000
Dispersed site warning signs (outside of wilderness)	Each	3	\$400	\$1,200
Campground warning signs	Each	2	\$400	\$800
Terwilliger Hot Springs entrance	Each	1	\$400	\$400
Total Cost:				\$4,400

P2 – Road Closure Devices: Close the existing gate on Road 1985115 to deter public access to a high-severity burned area with hazard trees, erosion and debris flow hazards, and an existing landslide that has removed much of the road prism at approximately MP 2.7. **No Cost.**

P10 – Closure - The Forest also plans to install hard closure devices (secure gates) at three locations near the entrance of the burned area – on Roads 1900 near the north and south ends of the burned area and on Road 1985, primarily to deter access to Terwilliger Hot Springs while it is under closure order. The forest closure orders will extend through the winter, and may remain in place for up to one year. The BAER assessment would include recommendations for similar closures, had the Forest not premptively decided to do so. **No Cost.**

Terwilliger Hot Springs Treatments

P5 – Hazardous Materials: Treatment Description - Extract and remove hazardous human waste from the two burned fiberglass toilet vaults adjacent to the Terwilliger Hot Springs developed recreation site. Capping the vaults would still leave an unacceptable risk to human health and safety – any possible release and resultant contamination of the ground surface, groundwater and/or surface water, in close proximity to a developed recreation site where concentrated primary use is water contact recreation, would have major public health consequences and a create a very high public health risk. If a release were to occur, the cost to clean up contaminated soil, water and vegetation would greatly exceed the estimated cost to remove the waste while it is still contained in the vaults.

Treatment Cost: Cost is estimated based on Forest Service administration of contract labor. Work may be completed by force account labor (at a reduced cost) if that is available at the time of implementation, but early implementation, prior to the rainy season is essential to prevent hazardous waste release at the site. **Total request is for \$9,000.**

P6 – Infrastructure Protection: *Treatment Description* - Remove the French drain located immediately above the top soaking pool, to reduce the risk of it plugging and overland flow delivering sediment, ash and organic debris directly into the upper soking pool, which is likely given the anticipated increased sedimentation from mobilization of fire-affected soils and organic materials upslope. **Total request is for \$3,500.**

Contract Cost Estimate				
Treatment	Units	# of Units	Unit Cost	Total Cost
P5 - Remove human waste from toilet vaults (pump)	Each	2	\$4,500	\$9,000
P6 - Remove French drain	Each	1	\$3,500	\$3,500
Total Cost				\$12,500

I. Monitoring Narrative:

Treatment monitoring will occur as part of the treatments for weeds, roads, and trail and hot springs infrastructure protection. No additional funding is requested for monitoring.

Part VI – Emergency Stabilization Treatments and Source of Funds

	and Source of F		NFS Lands		
		Unit	# of		Other
Line Items	Units	Cost	Units	BAER\$	\$
A. Land Treatments					
L1a - Invasives Detection/Treatment	acres	153	46	\$7,050	- \$0
L1b - Invasives Detection/Treatment (suppression repair)	acres	239	48	\$11,450	\$0
				\$0	\$0
Insert new items above this line!				\$0	\$0
Subtotal Land Treatments				\$18,500	\$0
B. Channel Treatments	_				
None				\$0	\$0
				\$0	\$0
				\$0	\$0
Insert new items above this line!				\$0	\$0
Subtotal Channel Treat.				\$0	\$0
C. Road and Trails					
RT2 - Storm Inspection and Response	days	1,800	4	\$7,200	\$0
RT13 - Trail Drainage	miles	10,000	0.5	\$5,000	\$0
RT14 - Trail Infrastructure and Protection	miles	15,000	0.5	\$7,500	\$0
Insert new items above this line!				\$0	\$0
Subtotal Road & Trails				\$19,700	\$0
D. Protection/Safety					
P1a - Road Hazard Signs	sign/post	600	2	\$1,200	\$0
P1b - Trail/Recreation Hazard Signs	each	400	11	\$4,400	\$0
P5 - Hazardous Materials (removal)	each	4,500	2	\$9,000	.\$0
P6 - Infrastructure Protection (hot springs pools)	each	3,500	1	\$3,500	\$0
				\$0	\$0
Insert new items above this line!				\$0	\$0
Subtotal Structures				\$18,100	\$0
E. BAER Evaluation					
Initial Assessment	report	estimate		\$60,000	
Insert new items above this line!					\$0
Subtotal Evaluation					\$0
F. Monitoring					
					\$0
				\$0	\$0
Insert new Items above this line!				\$0	\$0
Subtotal Monitoring				\$0	\$0
G. Totals				\$56,300	\$0
Previously approved					
Total for this request				\$56,300	

PART VII - APPROVALS

1.	Forest Supervisor (signature)	16/17/18 Date
2.	Regional Forester (signature)	Date